

Z-PATCH

100% Epoxy Concrete Repair

DESCRIPTION

Z-Patch is a heavy-duty, high compression strength floor patch for repairing and resurfacing damaged plant floors. It renews and repairs spalled and damaged floors, fills and eliminates damaged expansion joints, and anchors machinery.

FIRST-AID

Eyes: Flush with copious amounts of water lifting lids and removing contact lenses to ensure complete irrigation—get medical attention.

Skin: Flush with water and then wash with soap and water, launder contaminated clothing before reuse—get medical attention if irritation persists.

Inhalation: Remove to fresh air and assist breathing as necessary—get medical attention.

Ingestion: Do NOT induce vomiting. Give water to rinse mouth. Get medical attention.

DIRECTIONS

1. Ready floor by removing all loose material. Sweep away dirt. Degrease areas which have a thick build-up of grease.
2. Remove the cradle which contains Part B (pint) and 10 lbs. special aggregate.
3. Thoroughly mix Part A (which contains 12 lbs. special aggregate) until uniform.
4. Pour entire contents of Part (B) into Part (A), which is in the bottom of the pail. Mix Parts A & B for 2-3 minutes.
5. Add special aggregate from cradle to mixed Parts (A & B) to desired consistency, thick for troweling, thin for pouring.
6. Fill holes, cracks, crevices to level of existing floor. Feather edges with a trowel. Wet trowel with epoxy thinner and finish off to a smooth surface.

Note: You have 25-30 minutes to apply product to floor. Z-Patch dries in 12-18 hours for light traffic and 48-72 hours for heavy traffic. Each kit covers 15-18 sq. ft. at 1/4" thickness.

HMIS SYMBOL



Health	2
Fire	1
Reactivity	3
Personal Protection	0

Part A



Health	3
Fire	1
Reactivity	0
Personal Protection	0

Part B



Health	2
Fire	0
Reactivity	0
Personal Protection	0

Part C

CAUTION

Please refer to the SDS for more detailed precautionary measures, handling instructions and emergency procedures. **KEEP OUT OF REACH OF CHILDREN.**